StarTech.com
Hard-to-find made easy®

USB-C™ Quad-4K Docking Station - DisplayPort and HDMI - 100W PD

Product Diagram (DK31C4DPPD, DK31C4DPPDUE and DK31C4DPPDI)

Front View

Actual product may vary from photos

| Port		Specifications and Installation
1	3.5mm Audio Port	• Connect an **Audio Device** • **4 Position Audio Jack** for **Headset** use
2	USB-A Charging Port	• SuperSpeed USB 5Gbps (USB 3.2 Gen 1) • Supports USB BC 1.2 • Supports Apple Charging of up to 2.4A • Connect the **Docking Station** to a **SuperSpeed USB 5Gbps Peripheral** or **Storage Device** (e.g. flash drive), using a **SuperSpeed USB 5Gbps (USB 3.2 Gen 1) Cable**
3	USB-C Charging Port	• SuperSpeed USB 10Gbps (USB 3.2 Gen 2) • Supports charging of up to 3A 5V • Connect the **Docking Station** to a **SuperSpeed USB 10Gbps Peripheral** or **Storage Device** (e.g. flash drive), using a **SuperSpeed USB-C 10Gbps (USB 3.2 Gen 2) Cable**
4	Power Button	• Powered **ON** by default • **Solid White LED** indicates the **Docking Station** is receiving power and is powered **ON** • Press and release the **Power Button** to power **ON** the **Docking Station**

Side View

Actual product may vary from photos

Port		Specifications and Installation
5	Mounting Holes	• (Optional) Mount the **Docking Station**, using appropriately sized **Mounting Plate Assembly** (sold separately)
6	Lock Slot	• Secure the **Docking Station** to a stationary object

Rear View

Actual product may vary from photos

Port		Specifications and Installation
7	DC 20V Port	• Connect the **Docking Station** to a **Power Source**, using the **Universal Power Adapter**
8	USB-C Host Port	• SuperSpeed USB 10Gbps (USB 3.2 Gen 2) • Charge the **Host Device** while using the **Docking Station** • USB Power Deliver (PD) 5/9/12/15/20V • Connect the **Docking Station** to a to a **Laptop**, using the **SuperSpeed USB-C 10Gbps (USB 3.2 Gen 2) Host Cable**
9	USB-A Device Ports	• SuperSpeed USB 5Gbps (USB 3.2 Gen 1) • Maximum 0.9A for downstream charging • Connect the **Docking Station** to two **SuperSpeed USB 5Gbps Peripherals** and/or **Storage Devices** (e.g. flash drives), using a **SuperSpeed USB 5Gbps (USB 3.2 Gen 1) Cable**
10	RJ45 Port	• 10/100/1000 Mbps • Connect the **Docking Station** to a **Network Device**, using a **Network Cable**

To view manuals, FAQs, videos, drivers, downloads, technical drawings, and more, visit www.startech.com/support.

11	Video 1-4 DisplayPort Port/HDMI Ports	DisplayPort Ports: • Connect the **Docking Station** to a **DisplayPort Enabled Display Device**, using a **DisplayPort Cable** - or - HDMI Ports: • Connect the **Docking Station** to an **HDMI Enabled Display Device**, using an **HDMI Cable**

Package Contents

• Docking Station x 1
• Host Cable x 1
• Universal Power Adapter x 1
• Power Adapter Cords (NA/JP) x 1
• Quick-Start Guide x 1

Requirements

For the latest requirements, please visit:
www.startech.com/DK31C4DPPD or www.startech.com/DK31C4DPPDUE

DK31C4DPPDI: www.startech.com/DK31C4DPPDI

• Host Laptop with USB-C Port
   • USB PD Support

Installation

Notes: *Depending on your Host Laptop's operating system, the required drivers will automatically be installed when the Docking Station is connected and powered on. If the drivers do not automatically install, follow the steps below.*

1. Use a web browser to navigate to www.startech.com/DK31C4DPPD or www.startech.com/DK31C4DPPDUE.

2. On the Product page, click the Support tab located in the middle of the screen.

3. In the Drivers and Downloads section, click on the driver link that corresponds with the operating system running on the host laptop.

4. Once the download is complete, extract the contents of the file.

5. Click the appropriate driver for the version of operating system that you are running and follow the on-screen prompts to complete the installation.

Operation

RJ45 Port LED Indicators

LED Color	Status	Indication
Green	Solid	• Link speed is either 1000Mbps (1 GbE), 100Mbps, or 10Mbps
	Off	• No connection established
Amber	Flashing	• Network traffic detected
	Off	• No link established