

# Installation Guide

To use the USB Docking Station, you must first install the driver onto your computer.

**IMPORTANT:** The devices connected to USB Docking Station working only after the installation process is completed. You must complete the installation instructions before using any device connected to USB Docking.

After installing your software, connect the docking station to your computer and Windows plug-and-play will install the hardware drivers for each port.

## Installation

1. Turn on your computer.
2. Insert the CD into your computer's CD-ROM drive.

If setup does not begin automatically, click Start, Run, and enter D:\ USBDocking.exe (where D: is the path of your CD-ROM drive) and then click OK.



### Click USB Docking Install

1. Please follow the installation procedure until the software is completed done.

### Using USB Docking

After installing the docking station software, you are ready to connect USB Docking to your computer.

1. Connect the supplied AC power adapter to the AC power jack on USB Docking.
2. Connect one end of the USB cable to USB Docking and the other end into an available USB 2.0 port on your computer **(NOTE: Please always keep the docking connected to the power adapter supplied with the product).**

IMPORTANT: USB Docking will not function properly without the AC adapter plugged into an AC outlet. Do not connect any devices to USB Docking until the installation is completed.

### Installing the Default Device Drivers

Once you connect the docking station to your computer, the default drivers begin installing for each of the ports automatically.

NOTE: Please ensure you have the latest service packs installed.

Some hardware devices may prompt you to install the drivers.

To install the drivers:

1. Select "Install the software automatically (Recommended)" and click Next. The Found New Hardware Wizard program begins installing the hardware drivers. The Completing the Found New Hardware Wizard screen appears.
2. Click Finish and repeat as needed for each device.
3. Restart your computer.